1132113 (00 b Cx803 CO-320892 01 Ob. 11 (01 cx	NOTES
4	
	nesona quanti
	ese control de la control de l
	LEGEND
NOTES UNLESS OTHERWISE SPECIFIED:	
1. THE TERMINATION RESISTOR MUST BE PRESENT IN EVERY PANEL BUT IT MUST BE CONNECTED	
TO XCOM11 BY SHORTING XCOM11:1, XCOM11:2, XCOM11:3 AND XCOM11:4.	
^	N DESCRIPTION OF THE PROPERTY
2 VT IS THE VOLTAGE TRANSFORMER	110-44
2 CTs & VTs ARE TO BE CONNECTED TO THE METERS VIA FT-SWITCH	
4 H1 IS ANTI-CONDENSATION HEATER TO BE CONNECTED TO 127/220VAC	
, <u> </u>	
5 USE GROUP MARKER FOR GROUP MARKING	
6 USE FERRULING FOR CABLE MARKING	REFERENCE DRAWINGS
	DRAWING TITLE DRAWING NO.  DRAWING CONTROL SHEET CD-293969
$\sqrt{7}$ for external wiring of the panels refer cable scheduling of the substations & for testing	DIVINITY CONTINUE SILES
FOLLOW THE TEST DOCUMENTS	
8 NEUTRAL SHOULD NOT BE CONNECTED TO THI THERMOSTAT	
	A CALL
9. CONNECTOR RESISTOR R4 BETWEEN TERMINALS 3 AND 4 OF XCOM1 AND GROUND TERMINAL 4 OF XCOM1 USING	137230412
YELLOW GREEN WIRE.	F/= Comment
10 ALL THE TERMINAL BLOCKS HAVING EXTERNAL WIRING CONNECTIONS LIKE VT.CT.AC/DC TERMINAL BLOCKS SHOULD HAVE	BO ( 1/255 ) 6 1 1
WIRE CONNECTION ON THE SIDE OF TERMINAL BLOCK NOT CLOSE TO PANEL ACCESS DOOR	
	97 26 Riyaco 139
∠11  ALL THE FERRULES SHOULD BE OUTSIDE RACEWAY, NEAR CONNECTOR & EASILY READABLE WIHTOUT TURNING OR MOVING WIRES.	acting Govern
	A (C) (ME 10) 19
12 FOR CONNECTIONS/FERRULING PLEASE FOLLOW THE TABLE	AS-BULT BY DATE
13 FOR CONNECTIONS/FERRULING PLEASE FOLLOW THE TABLE ON SHEET 11	
13 FOR CONNECTIONS/FERRULING PLEASE FOLLOW THE TABLE ON SHEET 11	1 13/07 MRA DETAIL DESIGN MRA AS
14 WHEN CONNECTING ELECTRICAL WIRES FOR THE RELAYS MAKE SURE TO CONNECT ON THE SIDE MARKED 'A' FOR ALL PIN NUMBE	
TILLY CONTROLLED HOW THE REEX TO MAKE SORE TO CONTROL MAKED A TOK ALL THE ROMBE	REV. DATE BY DESCRIPTION CHIC. CERT. APPD
15 DC AUX.CONTACTS FOR MCB101 THRU MCB104 WITH RATING 130VDC 1A ARE DRY MECHANICAL ALARMS FOR DC MCB TRIP WITH	_0
	الشركة السروية للكهرياء
11 AS 'COM' & 12 AS 'NO'	Saudi Electricity Company
	BRASH BY MRA CHECKED BY AS SCALE NONE
16 TERMINAL 10 IN XC1 TO XC4 TO BE CLOSED IF CT CIRCUIT IS NOT EARTHED ANY OTHER PLACE	BRASH BY MAN ORDED BY AS SCALE NUMBER OF DATE COMPLETED
	ORYG DEPT. SNG DEPT.
$\ (6)\ _{1}$	THIS DRAWING IS NOT TO BE USED FOR APPROVAL/CERTEFICATION INFORMATION CONSTRUCTION OF ORGE PROPERTY OF THE PROVAL CERTEFICATION INFORMATION DOC NO. E-123456 REV NO. 00
	10 10 10 10 10 10 10 10 10 10 10 10 10 1
$a_{ancy}$	ed Electronics 4 RM WITHOUT RELAYS FOR AMR
	S/S 8162 REYADH SAUDI ARABIA
AEC	JOB ORDER NO. INDEX PLANT NO. DRAWING NUMBER SHEET NO. REV. NO
DRASSINO NO. 1982T NO. 807 NO. CD-300803 DT OF 11 01	11131113/00   P   C469   CD-320883   01 of 11   01   SEC PAP-A 12004/0
	SEC CAD-A 12004/D [DMS] (MECTOR)



















